

Inventory Completed – No Lead Services

We are pleased to announce that the District has successfully completed its system-wide service line inventory in compliance with current regulatory requirements. This important effort involved reviewing records, conducting field inspections, and coordination with property owners to ensure a thorough and accurate accounting of all service connections within the distribution system.

The results are excellent news for our community. Based on our efforts and our records there are **no lead service lines** as defined in federal regulations. This means our customers can be confident that the water reaching their homes and businesses is not impacted by lead service lines. Should you find a lead service line please contact us immediately. Your household plumbing may have lead solder, and we encourage you to review this with a licensed plumber.

Completing this service line inventory is a significant milestone in maintaining transparency, protecting public health, and ensuring compliance with state and federal drinking water standards. We thank our staff, contractors, and residents for their cooperation throughout this process. The completed inventory may be found at Albertson Water District office.